



Technical Bulletin SAMSUNG DCS063	
Issued By : N. Garner Date : 21/11/03 Approved : W. Wood. Date : 21/11/03	Signed :  Signed : 
Replaces Technical Bulletin : N/A	
Subject : System Diagnostics	Number of Pages : 1

Automatic System Diagnostics

Issues have been found with the Automatic System Diagnostics, MMC 854. It has been found that depending on the system and/or software level the system may reboot or freeze after carrying out the diagnostics program and may require a manual restart.

It is, therefore, recommended by the Technical Support Department that this feature is **NOT** used on the iDCS 100, iDCS 500 and OfficeServ 500.

These issues have been raised with Samsung Telecom HQ and as soon as this feature is fully operational a further Technical Bulletin will be released.