



technical bulletin



Technical Bulletin SAMSUNG DCS050	
Issued By : N. Garner Date : 13 / 10 / 2000 Approved : D. Ridley Date : 13 / 10 / 2000	Signed :  Signed : 
Replaces Technical Bulletin : N/A	
Subject : Upgrading Compact 2 and DCS to V6.10	Number of Pages : 1

When upgrading either a Compact 2 or DCS to V6.10 software, please be aware of the new MMC 220, ISDN Service Type. This MMC sets the type of equipment that is connected to an analogue extension port: either Voice, Group 3 fax, 3.1K Audio or a Modem. Incorrect setting of this MMC may cause analogue extensions to not be able to dial some numbers. If this setting does not match the setting of the called party, over ISDN, the call will fail due to incompatible device errors.

All analogue extensions are set to *Voice* in default and this setting should **NOT** be changed. If, however, a system is upgraded using PCMMC, this setting will default to *FAX3* (Group 3 Fax) and will need to be reset back to *Voice*.